

Product Quality Notice

Notice number: **PQN-10**

Affected product: **GA124 - all models**

Subject: **Missing jumper plug on GA124 boiler**

Buderus

Problem Statement

GA124 boilers produced between April 2013 and May 2013 (FD 304 – 305) were shipped missing the jumper plug on the 6-position vent damper receptacle on the Aquasmart control. The GA124 boiler does not require a vent damper. The jumper plug is necessary for the boiler to run.

► Qty Affected: 64

Problem Solution

All boilers in inventory have been reworked and production has been corrected to include the jumper plug on future shipments.

Field Action

If a customer suspects they may have an affected boiler they can contact technical support at 1-800-283-3787 for a free of charge jumper plug or to make alternate arrangements.




Fig. 1 GA124 series boiler

Figure 2




Fig. 2 Jumper plug location inside Aquasmart control

Buderus

Bosch Thermotechnology Corp.
50 Wentworth Ave
Londonderry, NH 03053
Tel: (603) 552-1100
Fax: (603) 965-7581
www.buderus.us