

# Product Information Notice

Models: GB142-24,30,45,60

Brand: Buderus

Subject: GB142 Gas Supply Pipe Update

# Buderus



**All work must be performed by a licensed contractor.**

## Summary

GB142 boilers manufactured between 2004 and 2008 were shipped with a corrugated stainless steel gas supply pipe (Figure 1). Moisture from re-circulating flue gas or leakage from the heat exchanger air vent can potentially damage the stainless steel supply pipe and may lead to pin hole corrosion and the potential for gas leakage.

In 2008 the gas pipe (p/n 76685) was redesigned to include a protective rubberized sleeve which provides additional protection against corrosion (Figure 2). This part is available as a free upgrade and the older unprotected gas pipes should be replaced during normal maintenance of the GB142 boiler.

For a replacement gas supply pipe, please contact customer service with model, serial number, and homeowner information at 1-866-642-3198.

Figure 1



Figure 2



# Buderus

Bosch Thermotechnology Corp.  
50 Wentworth Ave  
Londonderry, NH 03053  
Tel: (866) 642-3198  
Fax: (603) 965-7581  
[www.buderus.us](http://www.buderus.us)